

SPARE PARTS LIST

3-TON SPEED WINCH (STRAP)

Drawing No.	Part No.	Description	Quantity
1	WSS3003	Right-hand side plate	1
2	WSS3002	Left-hand side plate	1
3	WSSA001	Drum (strap)	1
4	WSS3001	Drive shaft	1
5	WSS3005	Double gear shaft	1
6	WA3005	Double gear	1
7	WSS3004	Body shaft	4
8	WB3001	Handle arm (right-hand)	1
9	PRH12	Revolving handle	1
10	WBA001	Ratchet gear	1
11	WBA002	Drive shaft collar	1
12	WBA3003	Brake pad	1
13	WSHPI ½	Stop washer	1
14	PN112	Lobe knob	1
15	NUTPLH12	M12 Half nut	1
16			
17	WSHP020	M20 Washer	1
18	STRAP001	Strap	1
19	WBA004	Double ratchet	1
20	WBS001	Ratchet spigot	1
21	NUTNYP12	M12 Nyloc nut (P type)	11
22	WSHP012	M12 Washer	11
23	SCAP0870	M8 x 70 Socket cap	1
24	SCAP 0640	M6 x 40 Socket cap	1
25	NUTNYP06	M6Nyloc nut	1
26	NUTPLH12	M12 Half nut	2
27	WSHS12	M12 Spring washer	2
28	WA3007	Spacer	1